

PUBLIC WORKS DEPARTMENT
GOVERNMENT OF ARUNACHAL PRADESH



OFFICE OF THE ASSISTANT ENGINEER,
KANTANG SUB - DIVISION : PWD : AP
KANTANG - 792120

No: KSD/W- 18/2025-26/ 2)

Dated Changlang the 04 June'2025

BUILDING SAFETY CERTIFICATE

It is to certified that existing building Vivekananda Kendra Vidyalaya at Changlang , P.O/P.S : Changlang, Dist : Changlang, Arunachal Pradesh is comprised of following details :-


Details Block's in School	Block (1)	Block (2)	Block (3)
No. of Floor's in the Block	1	2	4

The building owned/occupied by Vivekananda Kendra Vidyalaya School, Changlang have complied with the Building Safety Requirements in accordance with CPWD specifications and National Building Code Rules, and has been verified by the officers concerned of O/o- Assistant Engineer, Kantang Sub-Division, PWD, Kantang, A.P on 03/06/2025 in the presence of Principal, VKV School and that the said building/premises is fit for occupancy for running the school in accordance with the rule and subject to compliance of the specific conditions as appended.

1. No cracks identified.
2. Roof condition is good.
3. Sitting arrangement is good.
4. Stairs are good.
5. If any sign of distress in structural elements like beams, Column and Slab is observed during the life span of the building then kindly bring to the structural consultant.
6. Take care the growth of vegetation on the terrace and peripheral of the building does not occur.
7. Water proofing on the terrace to be properly maintain and ensure that there is no leakages in future.

This certificate is valid for only **One Year** which effect from 04/06/2025 to 04/06/2026.

Yours faithfully,


Assistant Engineer
Assistant Engineer
Kantang Sub-Division, PWD,
Kantang Sub-Division
Kantang AP
PWD, Changlang (A.P.)

No: KSD/ /2025-26/

Dated Changlang the June' 2025

Copy To :

1. The Executive Engineer, Changlang Division, PWD, Changlang, AP for information please.
2. Office Copy